2. component
3. solder
4. componentmask
5. soldermask
6. plated-drill
7. topsilk
8. bottomsilk
9. bottompaste
10. toppaste
11. topassembly
12. bottomassembly
13. fab



front, scale = 1:1.000
lqfp-100-0.5.pcb



back (mirrored), scale = 1:1.000
lqfp-100-0.5.pcb



frontmask, scale = 1:1.000
lqfp-100-0.5.pcb



backmask (mirrored), scale = 1:1.000
lqfp-100-0.5.pcb



plated-drill, scale = 1:1.000
lqfp-100-0.5.pcb



frontsilk, scale = 1:1.000
lqfp-100-0.5.pcb



backsilk (mirrored), scale = 1:1.000
lqfp-100-0.5.pcb



backpaste (mirrored), scale = 1:1.000
lqfp-100-0.5.pcb



frontpaste, scale = 1:1.000
lqfp-100-0.5.pcb



frontassembly, scale = 1:1.000
lqfp-100-0.5.pcb



backassembly (mirrored), scale = 1:1.000
lqfp-100-0.5.pcb

There are 4 different drill sizes used in this layout, 232 holes total

Symbol	Diam. (Inch)	Count	Plated?
˟	0.014	2	YES
+	0.030	8	YES
×	0.036	218	YES
∘	0.094	4	YES

Title: (unknown) - Fabrication Drawing
Author: DJ Delorie
Date: Sun Jun 7 04:36:05 2009 UTC
Maximum Dimensions: 2600 mils wide, 2600 mils high



Board outline is the centerline of this 10 mil rectangle - 0,0 to 2600,2600 mils

fab, scale = 1:1.000
lqfp-100-0.5.pcb